


F/G. 3






FIG. 5




FIG. 6A




FIG 6B







FIG. 6C







МОДЕ	M1'	M2	МЗ	M4	IM5
STEP UP	NO	OFF.	PWM ON	OFF	OFF
STEP DOWN	OFF.	PWN ON	OFF.	OFF	OFF
ENERGY RECEIVE	0FF	OFF	OFF	NO	NO
DATA RECEIVE	OFF.	OFF	OFF	NO	NO
DATA XMIT	NO	OFF	MODULATION ON	NO	NO

FIG. 8